

RFWV2.E177315 – Electrical Quick-connect Terminals – Component

Note: We are enhancing our systems and you may notice duplicate entries/missing/outdated data. During this interim period, please contact our Customer Service at <https://www.ul.com/about/locations>.

Electrical Quick-connect Terminals – Component

Xin Sheng Terminal Mfg Ltd
35 TAIYI 3RD ST
RENDE
TAINAN, 717 Taiwan

E177315

Marking: Company name and model designation.

Note: For additional marking information, refer to the [Guide Information Page](#).

Male Tabs, Model(s): 650-BS, 660-BS

Non-insulated quick-connect connectors for copper alloy tabs, Model(s): 70118, 7015, 7018, 70215T, 70225, 70225B, 70225C, 7025, 70252, 70253, 7025A, 7025T, 704-200, 704L, 707A, 707-G, 7091A, 7091D, 7091F, 7093A, 7093B, 7093C, 7093L, 7093ZY, 710B, 711, 71158, 7121AE, 7121C, 7121D, 7122, 71228, 712AE, 712C, 712D, 712D-20, 712D-200, 712F, 712F-20, 712F-21, 712FD, 712FD-20, 712H, 71310, 7133, 7151, 7169, 718, 71878H, 7188H, 718A, 7205, 7205A, 7205B, 75176ZY, 751A04, 751A04-S, 751BZY, 751C, 751D, 751-E, 7618-BS, 7625, 76250, 76253, 7625AT, 7625B, 7628AT, 7628B, 7645, 7648, 7818, 783, 783A, 787, S7025, S7091A, S7091F, S751A04

Non-insulated quick-connect connectors for steel and copper alloy tabs, Model(s): 704A, 704AB, 7093, 70935, 71155A, 7121A, 7121AB, 7121AT, 712A, 712AB, 712AT, 7628, 76280, S704A

Non-insulated quick-connect copper alloy tabs, Model(s): 1107, 1107W, 18702A, 18702AB, 18704, 18704A, 25002, 25002B, 25012, 25012B, 2510, 2518, 7187, 71871, 71878, 7187A, 7187AH, 7187H, 7188, 7250, 7250B, 8545, 8545A, 8548A

Non-insulated quick-connect plated copper alloy tabs, Model(s): 25007, 25007B

Quick Connect Terminals, Model(s): 70115, 70115A, 70115-BS, 70116, 70215, 70215A, 70215-BS, 70218, 70218-BS, 70315, 70315-BS, 704, 704B, 704-BS, 704T, 707, 707-BS, 707T, 709, 709A, 709-BS, 710, 710-BS, 710W7.2, 71155-BS, 712, 7120, 712030, 7121, 71210, 7121B, 7121-BS, 712B, 712-BS, 713, 713B, 713-BS, 7195, 7195A, 7195-BS, 7196, 741, 742, 751, 7513, 75176, 751A, 751A-BS, 751B, 751-BS, 751SQ, 751T, 752, 7522, 7522A, 7522-BS, 752B, 752-BS, 754, 7541, 75416, 75416A, 7541-BS, 754-BS, 75520, 75520-BS, 7583, 7584, 7585, 7585035, 7585-BS, 7585C, 7586, 7588, 7615, 7615-BS, 764, H704, H707, H751, S704, S707, S751, X751SQ

Quick-Connect Terminals, Model(s): 71155

Last Updated on 2022-03-10

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL's Follow-Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL's Follow-Up Service. Always look for the Mark on the product.

UL permits the reproduction of the material contained in the Online Certification Directory subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from the Online Certifications Directory with permission from UL" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "© 2022 UL LLC"